

Title	Visual Audit of Murwillumbah South and Dorothy_Wiliam Street Levees
Abstract	Visual Audit of Murwillumbah South and Dorothy & Wiliam Street Levees - March 2015
Resource locator	<p>Visual Audit of Murwillumbah South and Dorothy & Wiliam Street Levees - March 2015</p> <p>Name: Visual Audit of Murwillumbah South and Dorothy & Wiliam Street Levees - March 2015</p> <p>Protocol: WWW:DOWNLOAD-1.0-http--download</p> <p>Function: download</p>
Unique resource identifier	
Code	320cd8ba-b525-49ce-b6dc-c4d9348525b1
Presentation form	
Edition	14/10/2022
Dataset language	English
Metadata standard	
Name	ISO 19115
Edition	2016
Dataset URI	https://datasets.seed.nsw.gov.au/dataset/320cd8ba-b525-49ce-b6dc-c4d9348525b1
Purpose	Land and Resource Management
Status	On going
Spatial representation	
Type	vector
Spatial reference system	
Code identifying the spatial reference system	4283
Topic category	

Keyword set	
keyword value	
Originating controlled vocabulary	
Title	ANZLIC Search Words
Reference date	2008-05-16
Geographic location	
West bounding longitude	153.126068
East bounding longitude	153.540802
North bounding latitude	-28.456618
South bounding latitude	-28.23181
Vertical extent information	
Minimum value	-100
Maximum value	2228
Coordinate reference system	
Authority code	urn:ogc:def:cs:EPSG::
Code identifying the coordinate reference system	5711
Temporal extent	
Begin position	
End position	N/A
Dataset reference date	
Resource maintenance	
Maintenance and update frequency	As needed
Contact info	
Contact position	Data Broker
Organisation name	NSW State Emergency Service
Responsible party role	pointOfContact
Limitations on public access	
Responsible party	
Contact position	Data Broker
Organisation name	NSW State Emergency Service
Responsible party role	pointOfContact

Metadata point of contact

Contact position

Data Broker

Organisation name

NSW State Emergency Service

Responsible party role

pointOfContact

Metadata date

2024-03-25T10:00:22.984348

Metadata language